The doorbell transformer is located in the garage behind the cover panel for the in-floor heating controls. Be aware that there are **two** transformers attached to the 120 VAC service box. One transformer is dedicated to the heating control system and puts out 28 VAC (left). This voltage is standard for most industrial control systems. The second smaller transformer on the right is for the door bell and is rated for 18 VAC (ours was 21 VAC). DO NOT MIX UP these two transformers.

The smaller transformer on the right is for the door bell (**Notice the yellow tape**). The one on the left is for the heating control system for your unit.

It is not known if the yellow tape is used consistently throughout the condo, or not. Any feedback on this point would be helpful.

